


Material Identification

A 1pcs.
table top



B 4 pcs.
Threaded rod



C 4 pcs
Leg profile



D 4 pcs.
foot support




E 4 pcs.
Round nut





F 4 pcs.
foot insert




1 Locate threaded rod (B) by rotating
ot the compact table top(A)




2 Locate the the metal legs(C)
on the threaded rod (B)




Attention
Metal legs (C) should locked
on the corner part.



3 Locate the the foot support(D)
into the metal legs (C)



- 5** Locate the round nuts(E) on the foot support (D) then tighten by using art deep socket screwdriver (13 mm) in direction of arrow



- 6** Finally locate the foot inserts, and press until totally fix.

